





**insert the restriction clip into the gap
between the linkage and the cross bar**



close the hinge to its full closed position

